

EXISTING LIST OF CENTRALISED

SI No.	Description
1	Anchorage testing machine.
2	Brattice cloth.
3	Breathing apparatus (for rescue).
4	Burnside boring machine.
5	Capo lamps / LED Caplamps, their charges.
6	C.R.Sheet 1.6mm / 2 mm for w-strap.
7	ERW Steel pipes 100mm and 125mm for jpit props.
8	Flame safety lamp.
9	Fire Extinguishers of various types.
10	Local methane Detector.
11	Gravimetric dust sampler.
12	Gumboot/ Rubber knee boot.
13	Helmet.
14	Hollow Square Tube (49.5 x 49.5 x 3.6 mm) for steel cog/ chock.
15	M.S.channel 65mm x 125mm for pit prop.
16	M.S. plate 6mm / 8mm for bearing plate.
17	M.S.nut 20mm / ¾” for roof bolt.
18	Main locator.
19	Methanometer (Intrinsically safe Analogue and Digital type).
20	Miner’s canvas shoes.
21	Multi gas detector.
22	Personal dust sampler.
23	Rescue Tools.
24	Rescue Vans.
25	Roof bolt Threading m/c.
26	Roof bolt ith bearing plate and nut.
27	Roof bolting machine.
28	Safety Leather Shoes.
29	Safety Shoe for Women.
30	Shot Firing Cable.
31	Self Rescuer self contained,chemical oxygen type.
32	Steel cog / chock, DGMS approved.
33	Steel pit prop, DGMS approved.
34	Stone Dust.
35	Slack & Unslack Lime.
36	TMT bar 20mm for roof bolt.
37	Universal compressive testing m/c.
38	Water bottle.
39	W-Strap for roof support.